



# SL-9013

## Sway Bar Link - Repair Kit Mercury / Nissan / Suzuki / Chevrolet



**O.E.M. #:**


- F3XY-5A486A Kit
- 09159-10056 Nut
- 09165-10002 Washer
- 09320-10024 Bushing
- 01223-00291 Nut
- 54619-0B000 Bushing
- 54619-8B400 Bushing
- 54622-0B000 Washer
- 56112-50Y00 Bushing
- 56112-58Y00 Bushing
- 56112-W5000 Bushing
- 56113-50700 Washer
- 56113-60U05 Washer
- 56113-M3000 Washer
- 96057770 BUSHING



**Front or Rear  
 Suspension**

**( 2 or 4 ) Per  
 Vehicle**

Repair Kit  
 does not  
 include link.



<b>Napa #</b>	<b>McQuay #</b>	<b>Moog #</b>	<b>TRW #</b>
265-1319	SL-234	K-90128	18193

**APPLICATIONS:**

<b>Year</b>	<b>Make</b>	<b>Model</b>	<b>Location</b>	<b>Qty / Vehicle</b>
1993 - 2002	Mercury	Villager	Front & Rear	4
1993 - 2001	Nissan	Altima	Front	2
1990 - 1992	Nissan	Axxess - 2wd & 4wd	Front	2
1989 - 1999	Nissan	Maxima	Front	2
1987 - 1993	Nissan	Pulsar, NX	Front	2
1993 - 2002	Nissan	Quest	Front & Rear	4
1986 - 1999	Nissan	Sentra 2wd	Front	2
1987 - 1990	Nissan	Sentra 4wd	Front	2
1986 - 1992	Nissan	Stanza	Front	2
1995 - 1997	Nissan	200SX	Front	2
2002 - 2007	Suzuki	Aerio - 2 & 4wd	Front	2
1990 - 1998	Suzuki	Side Kick - 2wd	Front	2
1989 - 1998	Suzuki	Side Kick - 4wd	Front	2
1999 - 2005	Suzuki	Grand Vitara 2wd & 4wd	Front	2
1999 - 2004	Suzuki	Vitara 2wd & 4wd	Front	2
1996 - 1998	Suzuki	X-90	Front	2
2001 - 2006	Suzuki	XL-7 2wd & 4wd	Front	2
1989 - 1998	Chevrolet	Tracker	Front	2
1999 - 2004	Chevrolet	Tracker	Front	2
1989 - 1991	Geo	Tracker	Front	2

Manufactured in the

